



Dominik Drive looking northwest toward Glenhaven Drive January 2005 before rehabilitation project began by the city. Street was 38 feet wide with an asphalt surface.



Dominik Drive looking northwest toward Glenhaven Drive June 2005 after rehabilitation CIP project was completed. Street is now concrete 31 feet wide with a 6 foot sidewalk on the northwest side. A no parking zone is now necessary on the northwest side of the street because the width of the street was narrowed by 6 feet.