



This picture was taken near the intersection of Suffolk Avenue and Burt Street looking northbound. It presents the limited view that northbound vehicles have of opposing traffic coming around the corner. For example, the second truck from the right is limiting the ability of a northbound vehicle from seeing the white truck traveling southbound around the corner.



In the previous picture, it can be seen that the road curves to the right. However, due to the vehicles parked along the south side of Suffolk Avenue, it is difficult to see that after the road curves to the right, the road has two more curves.



This picture shows that with the parking allowed on the south side of the street, opposing traffic cannot easily pass.